



2. C-47 Photos. This was our flying classroom at Ft. Huachuca. The story of the aircraft would best be told by others. It was flying missions when I arrived in 1968. The photos show the aircraft before, during and after modification. SLAR and IR systems were installed at training stations pretty much like the observer would see them in the OV-1. Lots of 17L's got their initial systems training in this aircraft. Four of the photos show the aircraft in a minor accident, but it was repaired and returned to duty. Just prior to the OV-1's retirement 256 was at Davis Monthan AFB. I believe the aircraft found a new



































